


PART NUMBER:

BS171

NAME:

Specchietto "ELISSE"
Mirror "ELISSE"

SPARE PARTS - RICAMBI CLIENTE - ERSATZTEILE
PIEZAS DE REPUESTO - PECAS SOBRESSALENTES





BS171 (Specchietto SX completo)
(Complete LH mirror)




Portavetro completo
Complete Mirror-Body

BS171-01-KT



Asta completa di
grani e specchio
Complete auction
with the screws and
mirror



A080-02-KT



IMPORTANTE: per sostituire l'asta è necessario rimuovere lo specchio
IMPORTANT: for substitute the bar is fundamental remove the mirror

Snodo completo
Complete junction

R168-KT



GLS012-02

BS171-01-KT

A080-02-KT

VG05X05PI

B222

V06X20BB10.9K-ZB

BS774-03

VR06P